## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 7,100,065 B2

065 B2 Page 1 of 2

APPLICATION NO.: 10/630182

DATED: August 29, 2006

INVENTOR(S): Richard W. Adkisson

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the Title page, in Item (54), in column 1, in "Title", line 2, delete "SYNCHRONIZER" and insert -- SYNCHRONIZING --, therefor.

In column 1, line 2, delete "SYNCHRONIZER" and insert -- SYNCHRONIZING --, therefor.

In column 10, line 49, delete "b2c\_valid ff" and insert -- b2c\_valid\_ff --, therefor.

In column 16, line 66, in Claim 9, delete "sync ratio" and insert -- sync\_ratio --, therefor.

In column 17, line 48, in Claim 11, delete "signet" and insert -- signal --, therefor.

In column 18, line 25, in Claim 14, after "block" delete ",".

In column 18, line 65, in Claim 19, delete "b0\_set" and insert -- b0\_sel --, therefor.

In column 19, line 32, in Claim 22, delete "N/m≥1" and insert -- N/M≥1 --, therefor.

In column 20, lines 12-13, in Claim 26, delete "sync ratio" and insert -- sync\_ratio --, therefor.

In column 20, line 43, in Claim 29, after "generating a" delete "skew state" and insert -- skew\_state --, therefor.

In column 20, line 55, in Claim 30, delete "synch0" and insert -- syncb0 --, therefor.

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 7,100,065 B2 APPLICATION NO. : 10/630182 Page 2 of 2

DATED INVENTOR(S)

: August 29, 2006 : Richard W. Adkisson

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 20, line 57, in Claim 30, delete "signals." and insert -- signals to said core clock synchronizer controller portion. --, therefor.

Signed and Sealed this

Seventeenth Day of February, 2009

John Ooll

JOHN DOLL
Acting Director of the United States Patent and Trademark Office